HPFi

High Point, USA

Unapproved Upholsteries

(updated 10/28/26)

Date	Supplier	Pattern	Issue / Reason
12/31/16	Mayer Fabrics	Florentino	Material separates too easily fr. backer
01/02/17	KB Contract	Connect	Rips/shreds during upholstery
06/04/18	Nassimi	Seduction	Creases during sewing
06/04/18	Douglass Industries	Seduction	Creases during sewing
06/04/18	Mayer Fabrics	Verona	Creases during sewing
06/18/18	Momentum	Beeline EPU	Creases during sewing
06/27/18	Culp	Hathaway (Black only)	Creases/White line in surface
06/27/18	Momentum	Endurance EPU (Noir)	Creases/White line in surface
08/02/18	Culp	Hathaway (Navy only)	Creases/White line in surface
08/02/18	Momentum	Canter (Onyx only)	Creases/White line in surface
10/26/18	Momentum	Canter EPU (all colors)	Excessive puddling, too stretchy
02/04/19	Momentum	Bravo II (all colors)	Mottled, creases in pattern
07/08/19	ArcCom	Crystal (all colors)	Material separates under stress/pull
10/22/19	Douglass Industries	Funhouse (all colors)	Color rubs off easily
11/12/19	CF Stinson	Chaos (all colors)	Material unforgiving, curves puddle
05/26/20	Momentum	Eon EPU	Excessive puddling, too stretchy
08/24/20	Designtex	Luster	Excessive stretch, requires recutting
12/07/22	Anzea	Pacific-O	Shreds after cutting, separates with pull
04/20/23	Momentum	Follow CV	Too stiff to upholster
09/07/23	CF Stinson	Stride	Surface easily bruised, cannot be removed
03/04/24	Momentum	Nestle	Material separates under stress/pull
10/08/24	Momentum	Deka	Material separates under stress/pull
01/10/25	Momentum	Expo	Material too stiff, bunches, unforgiving
01/05/26	Mayer Fabrics	Ryder	Rips/shreds during upholstery
02/12/26	Momentum	Faux Mo	Ceases and steaming does not resolve
10/28/26	Culp	Dot Com	Formulation changed, not plyable