Assembly Instructions

Hyperwork

Meeting Table

Tools & Hardware Provided

- 5.5mm (7/32") Allen Wrench
- Bolts (4)
- Washers (4)

Step 1

Place the table top a smooth, clean work surface on the floor. Using two (2) washers on the bolts, secure one table bases to the understructure of the table top as shown at right with the Allen Wrench.





Step 2

Repeat the process used in Step 1 to attach the remaining table base to the understructure of the table top as shown at left.

Step 3

With assistance, turn the table with two (2) bases attached in an upright position.



NOTE: Be certain to retain the Allen Wrench. Periodically check that the bolts on the bases are secure. Moving the table to another room or location may require the bolts to be re-tightened.